CRAFTING IDEA

GB

Big pear out of
the kneading-cement

Used items:

34 211 000	Creative kneading-cement	320 g
30 076 000	Styrofoam-shape „Vario"	1 pc

Additionally you need:

Sharp-pointed stick as a pear-stalk
Container for kneading of the cement (e.g. bowl with lid)
Disposable gloves
PET spray bottle (item 38 798 000)
Brush
Small container with water
Stable support e.g. the lid of a plastic bucket
Poss. sandpaper (item 89 530 00)

Instructions:

1 Always wear plastic gloves while working!

2 Mix the cement with water in the ratio 9:1 (9 parts of cement : 1 part of water). This corresponds to about 35 ml. Stir the water slowly, gradually add it while constantly kneading. Knead the crumbly mixture with damp disposable gloves (if necessary, moisten several times) until the desired consistency is achieved.

Hint You can mix also, quickly and easily, the kneading-cement in a sealable container. Here also add the water gradually by stirring it constantly, then close the container and shake it well. That way there is less dust and the parts intermix perfectly. Knead more afterwards the crumbly mixture with wet disposable gloves (if necessary, moisten several times) until the mixture is malleable.

3 Insert the sharp-pointed upwards as a stalk onto the styrofoam-shape. As a first step, spread out the kneading-cement onto the styrofoam-ball by hands until it is completely and thinly coated.

4 As a second step, spread out the remaining cement mixture on the coated shape by hands and sculpt it pear-shaped. Potentially spread upwards the cement evenly with a slightly moistened brush.

5 If the cement is too dry for sculpting, moisten it slightly with the water from the spray bottle.

6 Let it dry at least for 1 day.

7 As desired, you can paint or decorate further the pear with metallic effects.

8 The entire drying period lasts for several days. After about 21 days the object is weatherproof.

Rayher.