



CRAFTING IDEA

Self-cast in a jiffy. Ribbed candles stylishly displayed.

WWW.RAYHER.COM

GB

Used items:

36 201 000 46 801 502 31 042 02	Casting mould Ribbed candle, twisted Decorative metal tray, ø 20 + 25 cm, eucalyptus Wax pellets, white	1 piece 1 piece 570 g
31 640 685	Colour pigments for wax, pastel	1 piece
85 493 000	Eucalyptus bundle with paper sleeve	1/3 bundle
31 589 000	Flat wick, FD19	60 cm

Additionally you need:

Stove, candle wax melter, scissors, cotton darner needle

Instructions:

- 1 Take the cotton darner needle to pierce a small hole in the middle of the bottom of the silicone casting mould and pull the wick through the resulting hole. Then lay the mould flat on a stable surface.
- 2 Place the metal wick holder over the opening of the casting mould and insert the other end of the wick into the hole of the wick holder.
- 3 Melt about 190 g of wax pellets per candle in a bain-marie (Prior to this, please carefully follow the instructions for melting wax, as there is a risk of burns!)
- TIP To dye the candle, add the colour pigment to the melted wax and mix well. Carefully pour the liquid wax into the mould.
 Flüssiges Wachs vorsichtig in die Form gießen.
- TIP The mould can be filled to different height levels.
- 4 Let it cool down thoroughly A sinkhole may occur while cooling down, which can be evened out by pouring in more wax. Allow the wax to cure fully. Take out the wick from the holder and carefully remove the silicone casting mould.
- 5 Place the demoulded candles on the metal tray and decorate with a few sprigs of eucalyptus.











Rayher.

WWW.RAYHER.COM

More craft ideas and additional material information can be found on our website.



