





CRAFTING IDEA

In shape in a flash. Black & white coaster. GB

WWW.RAYHER.COM



Used items:

 36 126 000
 Silicone casting mould Oval coaster
 1 piece

 36 990 00
 Casting powder Raysin 200
 approx. 125 g

 34 479 576
 Casting powder Raysin 250
 approx. 125 g

Additionally you need:

Water, mixing vessel Sandpaper if necessary

Instructions:

- 1 Mix the two casting powders, each with water, in separate vessels.
- 2 Pour in both casting compounds at the same time, each on one side of the casting mould.
- 3 Pour in the two colours simultaneously until the mould is completely full.
- 4 Let the Raysin dry for about 60 minutes. Soon thereafter, you can demould it. If needed, fix any uneveness using the sandpaper. Then allow your artwork to harden well, at best overnight.











* Without drying time

Rayher.

WWW.RAYHER.COM

More craft ideas and additional material information can be found on our website.

© 2023, Rayher Hobby GmbH

